




HANSAPRIMO

Installation and maintenance guide

**4940 2203**


I (ISO 3822)
EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +70°C



mpi.hansa.com/49402203

4942 2203 , 4942 2203 0037


I (ISO 3822)
EN 817
100 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
200 kPa (0.1 l/s)
max. +70°C









mpi.hansa.com/49422203

4956 2203 , 4956 2203 00676


I (ISO 3822)
EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +70°C



mpi.hansa.com/49562203






1










① ② ③




①





2.5
② ⑥






2.5

②




A





A











A



B








A1












G1






G2



G6





CLEANING.HANSA.COM