




HANSAPINTO

Installation and maintenance guide



**4504 2283**


EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +80°C



mpi.hansa.com/45042283

4501 2283


EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +80°C







mpi.hansa.com/45012283

4506 2283



EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +80°C



mpi.hansa.com/45062283



1








①







max.
1600 kPa






① ② ③






②

⑤















2.5


②



⑤ ⑥








A1











G1






G2



G6













②

③





22



cleaning.hansa.com