




HANSAPINTO

Installation and maintenance guide



**4504 2283**


EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +80°C



mpi.hansa.com/45042283

4501 2283


EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +80°C









mpi.hansa.com/45012283

4506 2283

EN 817
50 - 1000 kPa
0.10 l/s (300 kPa w/Controller)
max. +80°C



mpi.hansa.com/45062283










①





max.
1600 kPa





② ⑤















2.5


②



⑤ ⑥








A1











G1






G2







G6







22



cleaning.hansa.com