




# HANSAPINTO

Installation and maintenance guide



## 4502 2283


EN 817  
50 - 1000 kPa  
0.10 l/s (300 kPa w/Controller)  
max. +80°C



[mpi.hansa.com/45022283](http://mpi.hansa.com/45022283)

## 4505 2283


EN 817  
50 - 1000 kPa  
0.15 l/s (300 kPa)  
0.10 l/s (300 kPa w/Controller)  
max. +65°C







[mpi.hansa.com/45052283](http://mpi.hansa.com/45052283)

## 4507 3283



EN 817  
50 - 1000 kPa  
0.10 l/s (300 kPa w/Controller)  
max. +90°C



[mpi.hansa.com/45073283](http://mpi.hansa.com/45073283)



1












①



max.  
1600 kPa
















2.5




②

⑤ ⑥







2.5


A1



G1











G2






2.5

G6













22



[cleaning.hansa.com](https://cleaning.hansa.com)